
RESIN GRIP™

Non-slip Flooring System



Case History



COMMENTS

- The sheet vinyl used in the commercial kitchen was deteriorating after two years of service. Major symptoms included cracking (at seams, transitions and drains), splitting and peeling.
- The hot, wet conditions in these areas can lead to bacterial growth within the cracks/gaps and underneath the failed floor. A new floor had to be installed urgently, with a seamless, water-resistant epoxy well suited.
- After the vinyl was removed, it was discovered some sections of leveller underneath had been damaged by moisture. An epoxy leveller was used to re-level the surface in preparation for coating.
- A non-slip finish with an R12 rating was applied as per commercial kitchen requirements at the time.