## **RESIN GUARD™**

Protective Flooring System



## **Case History**



## COMMENTS

- The existing epoxy coating had been worn down and needed to be replaced.
- To prepare the heavily contaminated 1200m<sup>2</sup> workshop area, a high-pressure hot water rotary clean was administered and followed up with a diamond grind.
- Selection of the Kevlar<sup>®</sup>-reinforced Jaxxon 1525 was made due to its excellent wear and impact resistance. Two coats of were then applied by roller.