

## Case History



### PROJECT SUMMARY

<b>Client</b>	Thomas Borthwick & Sons
<b>Location</b>	Mackay, Queensland
<b>Colour</b>	Signal Red (R13)
<b>Area</b>	260m <sup>2</sup>
<b>Installer</b>	WJ Ashman

### COMMENTS

- Having successfully patched small areas of damaged flooring for over 18 months, the abattoir asked the installer to completely re-surface a 260m<sup>2</sup> section during a planned shutdown.
- A custom Resin Grip™ system was used to offer a durable, slip-resistant finish in the harsh commercial conditions.
- Jaxxon 1525 (basecoat) and 1505 (topcoat) were followed with an additional clear topcoat in the form of Jaxxon 1335. The aggressive caustic cleaners used in these facilities can interfere with the colour and gloss of pigmented films, so the clear topcoat was added to help protect the vibrant Signal Red finish.